

General Environmental Incident Summary

Incident: 5353

Notice: 3/24/2017

Occurred: 3/23/2017 1300

DEM Incident No:

No Further Action: ☒

Responsible Party: Montana-Dakota Utilities Co.

County: Burleigh

Twp Rng Sec Qtr: 138 80 3

Lat Long + Method: 46.79608 -100.75970 Interpolation from map

Location Description: 909 Airport Rd., Bismarck, ND 58504

Submitted By Info: Andy McDonald
Montana-Dakota Utilities Co
400 N 4th St
Bismarck ND 58501

Received By Info:

Contact Info:

400 N 4th Street
Bismarck ND

Affected Medium: 04 - water and soil

Near. Occupied Bldg: 300 Feet

Type of Incident: Recloser leak

Release Contained: Yes

Reported to NRC: No

Contaminant: Mineral oil (0 ppm PCB)

Volume of Release: 20 gallons

Duration of Release:

Agriculture Related: No

EPA Extremely

Hazardous Substance: No

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

Two oil filled reclosers were knocked over in our service yard.

Risk Evaluation:

None

Potential Env. Impacts:

None expected other than the contaminated material which will be removed from the site and disposed of at the appropriate facilities.

Action Taken/Planned:

An earthen berm was constructed to contain the oil on our site. Sorbent pads were used to soak up the oil from the soil and a few standing puddles of water. Sorbent socks were placed at all storm water exit points and around the nearest storm water drain as an added precaution. Even though the oil has been contained onsite, as a precautionary measure, the City of Bismarck - Public Works Department was notified.

Wastes Disposal Location:

Material will be disposed of at the appropriate facilities.

Other Agencies Involved:

City of Bismarck- Public Works Dept.

Updates

Date: 3/24/2017 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Notes:

According to the report, mineral oil was released. Emily Tintes Schiwal with Division of Waste Management will follow up.

Updated Volume: None at the time of this update

Date: 3/24/2017 **Status:** No Further Action Requested

Author: Tintes Schiwal, Emily

Notes:

Laboratory results from the 2 units that spilled are in the corresponding folder and show 0ppm PCBs. MDU staff had this contained on their property. No further action appears to be needed.

Updated Volume: None at the time of this update